

Multimeters

[Choosing](#) | [Digital](#) | [Analogue](#) | [Voltage & Current](#) | [Resistance](#) | [Diode](#) | [Transistor](#)

Next Page: [Resistance](#)

Also See: [Meters](#) | [Voltage and Current](#)

Multimeters are very useful test instruments. By operating a multi-position switch on the meter they can be quickly and easily set to be a **voltmeter**, an **ammeter** or an **ohmmeter**. They have several settings (called 'ranges') for each type of meter and the choice of AC or DC. Some multimeters have additional features such as transistor testing and ranges for measuring capacitance and frequency.



Liquid-Crystal Display (LCD)

Choosing a multimeter

The photographs below show modestly priced multimeters which are suitable for general electronics use, you should be able to buy meters like these for less than £15. A **digital multimeter** is the best choice for your first multimeter, even the cheapest will be suitable for testing simple projects.

If you are buying an **analogue multimeter** make sure it has a **high sensitivity** of 20k Ω /V or greater on DC voltage ranges, anything less is not suitable for electronics. The sensitivity is normally marked in a corner of the scale, ignore the lower AC value (sensitivity on AC ranges is less important), the higher DC value is the critical one. Beware of cheap analogue multimeters sold for electrical work on cars because their sensitivity is likely to be too low.

Digital multimeters

All digital meters contain a battery to power the display so they use virtually no power from the circuit under test. This means that on their DC voltage ranges they have a very high resistance (usually called input impedance) of $1\text{M}\Omega$ or more, usually $10\text{M}\Omega$, and they are very unlikely to affect the circuit under test.

Typical ranges for digital multimeters like the one illustrated:
(the values given are the maximum reading on each range)

- DC Voltage: 200mV, 2000mV, 20V, 200V, 600V.
- AC Voltage: 200V, 600V.
- DC Current: 200 μA , 2000 μA , 20mA, 200mA, 10A*.
- AC Current: None. (You are unlikely to need to measure this).
- Resistance: 200 Ω , 2000 Ω , 20k Ω , 200k Ω , 2000k Ω , Diode Test.

*The 10A range is usually unfused and connected via a special socket.

Digital meters have a special [diode test](#) setting because their resistance ranges cannot be used to test diodes and other semiconductors.



Digital Multimeter
Photograph © [Rapid Electronics](#)

[Top of page](#) | [Choosing](#) | [Digital](#) | [Analogue](#) | [Voltage & Current](#) | [Resistance](#) | [Diode](#) | [Transistor](#)

Analogue multimeters

Analogue meters take a little power from the circuit under test to operate their pointer. They must have a high sensitivity of at least $20\text{k}\Omega/\text{V}$ or they may upset the circuit under test and give an incorrect reading. See the section below on [sensitivity](#) for more details.

Batteries inside the meter provide power for the resistance ranges, they will last several years but you should avoid leaving the meter set to a resistance range in case the leads touch accidentally and run the battery flat.

Typical ranges for analogue multimeters like the one illustrated:
(the voltage and current values given are the maximum reading on each range)



Analogue Multimeter
Photograph © [Rapid Electronics](#)

- DC Voltage: 0.5V, 2.5V, 10V, 50V, 250V, 1000V.
- AC Voltage: 10V, 50V, 250V, 1000V.
- DC Current: 50 μ A, 2.5mA, 25mA, 250mA.
A high current range is often missing from this type of meter.
- AC Current: None. (You are unlikely to need to measure this).
- Resistance: 20 Ω , 200 Ω , 2k Ω , 20k Ω , 200k Ω .
These resistance values are in the middle of the scale for each range.

It is a good idea to leave an analogue multimeter set to a DC voltage range such as 10V when not in use. It is less likely to be damaged by careless use on this range, and there is a good chance that it will be the range you need to use next anyway!

Sensitivity of an analogue multimeter

Multimeters must have a high sensitivity of at least 20k Ω /V otherwise their resistance on DC voltage ranges may be too low to avoid upsetting the circuit under test and giving an incorrect reading. To obtain valid readings **the meter resistance should be at least 10 times the circuit resistance** (take this to be the highest resistor value near where the meter is connected). You can increase the meter resistance by selecting a higher voltage range, but this may give a reading which is too small to read accurately!

On any DC voltage range:

Analogue Meter Resistance = Sensitivity \times Max. reading of range

e.g. a meter with 20k Ω /V sensitivity on its 10V range has a resistance of 20k Ω /V \times 10V = 200k Ω .

By contrast, **digital multimeters** have a constant resistance of at least 1M Ω (often 10M Ω) on all their DC voltage ranges. This is more than enough for almost all circuits.

[Top of page](#) | [Choosing](#) | [Digital](#) | [Analogue](#) | [Voltage & Current](#) | [Resistance](#) | [Diode](#) | [Transistor](#)

Measuring voltage and current with a multimeter

1. **Select a range** with a maximum greater than you expect the reading to be.
2. **Connect the meter**, making sure the leads are the correct way round.
Digital meters can be safely connected in reverse, but an analogue meter may be damaged.
3. **If the reading goes off the scale:** immediately disconnect and select a higher range.

Multimeters are easily damaged by careless use so please take these precautions:


- Always disconnect the multimeter before adjusting the range switch.
- Always check the setting of the range switch **before** you connect to a circuit.
- Never leave a multimeter set to a current range (except when actually taking a reading).

The greatest risk of damage is on the current ranges because the meter has a low resistance.

Measuring voltage at a point

When testing circuits you often need to find the voltages at various points, for example the voltage at pin 2 of a 555 timer chip. This can seem confusing - where should you connect the second multimeter lead?

- Connect the **black** (negative -) lead to 0V, normally the negative terminal of the battery or power supply.
- Connect the **red** (positive +) lead to the point you where you need to measure the voltage.
- The **black** lead can be left permanently connected to 0V while you use the **red** lead as a probe to measure voltages at various points.
- You may wish to fit a crocodile clip to the **black** lead of your multimeter to hold it in place while doing testing like this.




Measuring voltage at a point.

Voltage at a point really means the voltage difference between that point and 0V (zero volts) which is normally the negative terminal of the battery or power supply. Usually 0V will be labelled on the circuit diagram as a reminder.

Reading analogue scales

Check the setting of the range switch and **choose an appropriate scale**. For some ranges you may need to multiply or divide by 10 or 100 as shown in the sample readings below. For AC voltage ranges use the **red** markings because the calibration of the scale is slightly different.



Analogue Multimeter Scales

These can appear daunting at first but remember that you only need to read **one** scale at a time! The top scale is used when measuring resistance.

Sample readings on the scales shown:

DC 10V range: 4.4V (read 0-10 scale directly)

DC 50V range: 22V (read 0-50 scale directly)

DC 25mA range: 11mA (read 0-250 and divide by 10)

AC 10V range: 4.45V (use the red scale, reading 0-10)

If you are not familiar with reading analogue scales generally you may wish to see the [analogue display](#) section on the general meters page.

[Top of page](#) | [Choosing](#) | [Digital](#) | [Analogue](#) | [Voltage & Current](#) | [Resistance](#) | [Diode](#) | [Transistor](#)

Measuring resistance with a multimeter

To measure the resistance of a component it must not be connected in a circuit. If you try to measure resistance of components in a circuit you will obtain false readings (even if the supply is disconnected) and you may damage the multimeter.

The techniques used for each type of meter are very different so they are treated separately:

Measuring resistance with a **DIGITAL** multimeter

1. **Set the meter to a resistance range greater than you expect the resistance to be.**

Notice that the meter display shows "off the scale" (usually blank except for a 1 on the left). Don't worry, this is not a fault, it is correct - the resistance of air is very high!

2. **Touch the meter probes together and check that the meter reads zero.**
If it doesn't read zero, turn the switch to 'Set Zero' if your meter has this and try again.
3. **Put the probes across the component.**
Avoid touching more than one contact at a time or **your** resistance will upset the reading!

Measuring resistance with an **ANALOGUE** multimeter

The resistance scale on an analogue meter is normally at the top, it is an unusual scale because it reads **backwards** and is **not linear** (evenly spaced). This is unfortunate, but it is due to the way the meter works.

1. **Set the meter to a suitable resistance range.**
Choose a range so that the resistance you expect will be near the middle of the scale. For example: with the scale shown below and an expected resistance of about $50\text{k}\Omega$ choose the $\times 1\text{k}\Omega$ range.
2. **Hold the meter probes together and adjust the control on the front of the meter which is usually labelled " 0Ω ADJ" until the pointer reads zero (on the RIGHT remember!).**
If you can't adjust it to read zero, the battery inside the meter needs replacing.
3. **Put the probes across the component.**
Avoid touching more than one contact at a time or **your** resistance will upset the reading!


Reading analogue resistance scales

For **resistance** use the **upper scale**, noting that it reads backwards and is not linear (evenly spaced).

Check the setting of the range switch so that you know by how much to multiply the reading.

Sample readings on the scales shown:
 $\times 10\Omega$ range: 260Ω
 $\times 1\text{k}\Omega$ range: $26\text{k}\Omega$

If you are not familiar with reading analogue scales generally you may wish to see the [analogue display](#) section on the general meters page.



Analogue Multimeter Scales


The resistance scale is at the top, note that it reads backwards and is not linear (evenly spaced).

Testing a diode with a multimeter

The techniques used for each type of meter are very different so they are treated separately:

Testing a diode with a **DIGITAL** multimeter

- Digital multimeters have a special setting for testing a diode, usually labelled with the diode symbol.
- Connect the **red** (+) lead to the anode and the **black** (-) to the cathode. The diode should conduct and the meter will display a value (usually the voltage across the diode in mV, 1000mV = 1V).
- Reverse the connections. The diode should NOT conduct this way so the meter will display "off the scale" (usually blank except for a 1 on the left).



Diodes

a = anode
k = cathode

Testing a diode with an **ANALOGUE** multimeter

- Set the analogue multimeter to a low value resistance range such as $\times 10$.
- It is essential to note that **the polarity of analogue multimeter leads is reversed on the resistance ranges**, so the **black** lead is positive (+) and the **red** lead is negative (-)! This is unfortunate, but it is due to the way the meter works.
- Connect the **black** (+) lead to anode and the **red** (-) to the cathode. The diode should conduct and the meter will display a low resistance (the exact value is not relevant).
- Reverse the connections. The diode should NOT conduct this way so the meter will show infinite resistance (on the left of the scale).

For further information please see the [diodes](#) page.

You may find it easier to test a diode with the [simple tester](#) project.


Testing a transistor with a multimeter



Set a digital multimeter to diode test and an analogue multimeter to a low resistance range such as $\times 10$, as described above for testing a diode.

Test each pair of leads both ways (six tests in total):

- The **base-emitter (BE)** junction should behave like a diode and **conduct one way only**.
- The **base-collector (BC)** junction should behave like a diode and **conduct one way only**.
- The **collector-emitter (CE)** should **not conduct either way**.



Testing an NPN transistor

The diagram shows how the junctions behave in an NPN transistor. The diodes are reversed in a PNP transistor but the same test procedure can be used.

For further information please see the [transistors](#) page. You may find it easier to test a transistor with the [simple tester](#) project.

Some multimeters have a 'transistor test' function, please refer to the instructions supplied with the meter for details.

[Top of page](#) | [Choosing](#) | [Digital](#) | [Analogue](#) | [Voltage & Current](#) | [Resistance](#) | [Diode test](#) | [Transistor](#)

Next Page: [Resistance](#) | [Studying Electronics](#)

- [Electronics Club Home Page](#)
 - [Site Map](#)
 - [Example Projects](#)
 - [Construction of Projects](#)
 - [Soldering Guide](#)
 - [Study Electronics](#)
 - [Electronic Components](#)
 - [Circuit Symbols](#)
 - [Membership](#)
 - [Frequently Asked Questions](#)
 - [Links to other Electronics sites](#)
-

